

Product Safety Recall



ZERO TOWER SAFETY HARNESS

SKU: HTP1679SML-HTP1679UNI-HTP1679XXL

Manufactured between October 2022 and February 2024

Defect: An assembly error of the shoulder strap adjustment buckle.

Hazard: This assembly error poses a significant risk as it may cause premature wear of the webbing on the shoulder strap, compromising user safety in the event of a fall or loss of control during work positioning, thereby increasing the risk of serious injury.

What to do: For immediate safety, discontinue use and check the product labelling for the manufacture date. If the harness falls within the manufacturing period of October 2022 to February 2024, please return the product to either the place of purchase or directly to ZERO Height Safety. We will inspect the affected product and repair or replace it at no cost.

Contact details: Return the product to either the place of purchase or to ZERO Height Safety at 16 Waimakariri Park Drive, Kainga, Christchurch 8083.

phone: 0800 357 003

email: sales@zeroheightsafety.com

online: zeroheightsafety.com

ZERO HEIGHT SAFETY (NZ/AU) LIMITED

16 Waimakariri Park Drive,
Kainga, Christchurch 8083
New Zealand

See www.recalls.govt.nz for
other New Zealand consumer product recalls