

FLAMMABLE OR EXPLOSIVE ATMOSPHERE

OR DUSTS WHICH COULD IGNITE
BY SPARK OR OPEN FLAME,
HAVE THE RISK OF EXPLODING
OR SPONTANEOUS
COMBUSTION.

FLAMMABLE GASES, VAPOURS

Clothing can easily be ignited and will

burn fiercely if it is saturated with oxygen







CONVEYOR BELTS.

Disclaimer

Every effort has been made to ensure that the information set out in this document is accurate. The information provided does not replace or alter the laws of New Zealand and other official guidelines or requirements. The information provided by ZERO Height Safety should not be used as a substitute for business, legal or any other professional advice. ZERO Height Safety does not accept any responsibility or liability whatsoever, whether in contract, tort, equity or otherwise, for any action taken, or reliance placed, as a result of reading any part, or all, of the information in this document for any error, inadequacy, deficiency, flaw in or omission from the information provided in this document. All references to other websites or organisations not within ZERO Height Safety are provided for convenience only and are not, and should not be taken as, endorsement of those websites or any information contained in those websites. ZERO Height Safety does not accept any legal liability for any damage or loss that may result, either directly or indirectly, from any information contained in this document or any actions taken as a result of the content of this document.